

BUILDING SAFETY CERTIFICATE

No.

Dated: 20/06/2023

Certified that the existing building Rotary English School (name of the building or premises) at S.no- 356/2, Malpur Road, Dondaicha, Tal-Shindkheda, Dist-Dhule (address) comprised of basement(s) and Ground Floor, First Floor, Second Floor (upper floors) owned /occupied by Dondaicha Education society's, Dondaicha Tal-Shindkheda Dist-Dhule (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Works Department (Name of Department/ Govt.) on 20/06/2023 (date of inspection) in the presence of Satishranjan Banik (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes I - X (X/XII) with effect from 20/06/2023 for a period of three (3) years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 20/06/2023 at Dondaicha by

* Strike out whichever is not applicable.

जावक क्रमांक: 261/2023
 उपविभागीय अभियंता
 सा.वा.उपविभाग, दोंडाईचा
 दिनांक- 20/06/2023

Signature with Seal: [Signature]
Deputy Engineer
P.W.D. Sub-Dn. Dondaicha

Name : _____

Designation : _____

Name & Address of Department/ Office: _____

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

[Signature]

PRINCIPAL

Smt.M.T.Rotary English School
 Dondaicha, Tal.Shindkheda (Dhule)

[Signature]

PRESIDENT

DONDAICHA EDUCATION SOCIETY
 DONDAICHA, DIST.DHULE